



SOUTH DELHI MUNICIPAL CORPORATION
OFFICE OF THE ASSISTANT ENGINEER (M-IV) NGZ
ROOM NO. 507, 5TH FLOOR, ZONAL OFFICE BUILDING
DHANSA STAND, NAJAFGARH, NEW DELHI-110043

Dated: 30/3/18


No.AE(M-IV)NGZ/2017-18/D-293


Structural Stability Certificate.

This is in reference to letter received in this office vide dairy no. 815 dated 21.3.2018 wherein, Manager New Sainik Sr. Sec. Public School Qutub Vihar, P.O. Goyala Dairy, New Delhi - 110071 has applied for structural stability certificate.

In this regard, it is stated that the building of New Sainik Sr. Sec. Public School Qutub Vihar, P.O. Goyala Dairy, New Delhi - 110071 has been inspected by JE Incharge as per the drawings supplied to this office and it is found that the building is structurally safe as per the appearance at site verification". The Structure Stability Certificate is issued based on the certificate granted to building by the S.D. Gupta & Associates, Structure Engineer, Architect, Chamber No. 416, Jaina Tower-I, district Centre, Janakpuri, New Delhi - 110058, MCD License No. SE-27 Dt. 17.1.2018. It is applicable subject to necessary permission/NOC be obtained from EE(Building) for building bye-laws, Delhi Fire Service, Delhi Police and Delhi Jal Board etc.

Manager
New Sainik Sr. Sec. Public School
Qutub Vihar, P.O. Goyala Dairy,
New Delhi - 110071


30/3/18
Asstt. Engineer/M-IV
Najafgarh Zone/SDMC
Asstt. Engineer
GZ - SDMC


Manager
New Sainik Public School
Qutub Vihar, Ph-I
Gyola Dairy N.D.-71


Principal
NEW SAINIK PUBLIC SCHOOL
Qutub Vihar Phase-1
New Delhi-110071